AVILOO
BATTERY DIAGNOSTICS

FLASH TEST REPORT

Execution

State of charge	37 %
Date	13/01/2025 10:30:32
Executed by	AURES Holdings

Vehicle

Brand	Hyundai
Model	Kona - 64 kWh
VIN	KMHK581GFKU049927
Mileage	120,609 km

Analysis Result

AVILOO SCORE 99 / 100

High voltage battery usage and history
Analysis of charging & driving behavior — 69 / 70

High voltage battery performance
Analysis of cell voltages and module temperatures. — 30 / 30

High voltage battery control unit
Check of signals and calculations of the battery management control unit. — ✔

Vehicle communication interface
Check of communication via the diagnostic interface. — ✔

Dr. Marcus Berger
CEO and Partner

DI Wolfgang Berger MBA
CSO and Founder

DI Nikolaus Mayerhofer
CTO and Founder

CARA Approved Battery Health Check

EXPLANATION OF THE BATTERY FLASH TEST

ANALYSIS METHOD

The analysis performed is a combined result of: The communication quality between the diagnostic hardware AVILOO Box and the on-board diagnostic interface of the vehicle. The live battery data and data that indicates the previous use of the high voltage battery, which is made available to the AVILOO Box by the battery management system during the measurement. The plausibility check and classification of the battery condition using the collected values and a comparison with the AVILOO Battery Cloud using Big Data algorithms.

FLASH TEST EXECUTION PROTOCOL

10:30:28 AVILOO Box connected.
✔ FLASH Test started.
✔ Vehicle detected.
✔ Starting data acquisition.
✔ Finished data acquisition.
✔ Analyzing data.
✔ Analysis completed.

DETAILED RESULTS OF PERFORMED CHECKS

Vehicle Information

VIN	KMHK581GFKU049927
Date	13/01/2025 10:30:32
Mileage	120,609 km

Measurements High Voltage System

Battery temperature	-1 °C
Maximum cell temperature deviation	0 °C
Pack voltage	351.9 V
Maximum cell voltage deviation	0 mV
Peak current during check	-7.99 A
State of Health (SoH - read from car manufacturer)*	100 %

*The SoH shown here was not calculated by AVILOO but corresponds to the SoH read out from the battery management system and calculated by the manufacturer. AVILOO therefore does not guarantee the correctness of this SoH.

AVILOO BATTERY DIAGNOSTICS
AVILOO GmbH
IZ NÖ-Süd, Straße 16, Objekt 69/5
2355 Wiener Neudorf
Austria
Tel: +43 2236 374 036
Mail: info@aviloo.com
Web: www.aviloo.com
UID Nr.: ATU 737 81605
FN: 502117 h